

2. Connect the data output(s). The A / B / A - B outputs are used with an integrator or PC-based data acquisition system; the chart output is for a strip chart recorder. Polarities and full scale range are indicated in the figure below. (Set the recorder/DAQ for the same voltage scale.)
3. Connect the main power cord.




Figure 9: Electrical connections